

What causes bubbles on the laminating surface?

Last Modified on 12/27/2018 10:57 am CST

Sometimes paper has dust or specks on it which minimizes the effectiveness of the adhesive. Make sure the surface space is clean before laminating. Heavily printed sheets, especially those with large dark areas, are at times difficult to laminate with a pouch laminator. Some materials that cause problems include, but are not limited to, coated papers, photographs or high gloss paper.
